

Picture Report



101 Sample St.
Winnipeg Mb.

Prepared for: Sample Report (Homowner/Insurance Co/Property Management Co)

Prepared by: Emond Siding & Roofing Co., Inc
Leo Emond

,

Emond Siding & Roofing Co., Inc

11:10 March 16, 2012

Page 1 of 6
Sample inspection.alb6



Windblown Shingles. Exposed plywood.



Fractured top of Tab.



Contaminated Self sealing strip with dust.



Fracture of the top of shingle tab. Due to wind lifting tab.



Example of the continouse effect of wind lifting tab,causing fracture.



Wind blown shingle.



Damage to all slopes



North Slope Fractures



Hail hit to shingle



Damage to stucco



Hits to aluminum eaves troughs